



VISUAL INSPECTION REPORT

Job Details

Client : PT. Armada Gema Nusantara
Project Name : CMP Project
P.O. Number : 4500215518
Location : HCML FIELD MADURA Straits, East Java
Installation : FPSO KAS III
Date of Inspection : 2024-02-20
Report No : 20AGN22191410PP371
AG IRM Project No : 20AGN2219
Module : M35
Component ID : 1-BA200-16-PW-7016-N
Component Type : Piping
Material : PIPE SMLS B444 Gr UNS N06625
Design Temperature : 107
Operating Temp : 25,5
Design Pressure : 32,8 Barg
Operating Pressure : 25,5 Barg
Rep Line : No
Corrosion Loop : 094-PW-A
Line From : SP-1620
Line To : 1"-AE200-16-PW-7018-N
P&ID : PID-3502

Inspection Summary

Table with 3 columns: Isometric Index, Results, Rectification WO No. Row 1: S, s, s

External Inspection Checklist for Process Piping

1-BA200-16-PW-7016-N

Section 1 - Structural

- a) Check and ensure expansion joints are not bent out of shape.
b) Check for any dents and misalignments, overhung, inadequate

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: N/A, s, See photo pages. Row 2: N/A, s, See photo pages

Section 2 - Piping Supports

- a) Check for missing supports that can cause the pipe to rupture under weight.

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: Checkmark, s, See photo pages

Section 3 - Coating

- a) Assess the coating condition of the piping system.

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: N/A, s, See photo pages

Section 4 - Leaks

- a) Check for leaks and identify locations.

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: N/A, s, See photo pages

Section 5 - Corrosion

- a) Identify corroded areas and record them. Take measurements and record pit depth.

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: N/A, s, See photo pages

Section 6 - Insulation and Insulation Penetrations

- a) Ensure all cladding is sealed.
b) Seal all exposed areas.
c) Expose some insulation are not vibrating or cracking.

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: N/A, s, See photo pages. Row 2: N/A, s, See photo pages. Row 3: N/A, s, See photo pages

Section 7 - Small Bore Attachments

- a) Ensure all small bore attachment are not vibrating or cracking.

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: N/A, s, See photo pages

Section 8 - Threaded Plugs

- a) Check condition of threaded plugs to ensure they are not corroded.

Table with 3 columns: Status, Discrepancy, Photo ref. Row 1: N/A, s, See photo pages

Legend

- Status Checkmark : Drawing as per actual condition, no anomaly
Status X : Drawing as per actual condition, found anomaly
Status N/A : Not exist at drawing and actual condition, no access for inspection

Comments

test
tes
tes

Table with 4 columns: Name, Qualification, Signature, API Inspector. Row 1: Name: Ercarter E. Silalahi, Qualification: API 570/API 510, Signature: [Handwritten Signature], API Inspector



PT. AG IRM SERVIS INDONESIA



ABS In-Water Specialist
Cert No. 21-4655696-A
ABS ESP Hull Gauging
Cert No. 21-4655692-A
ABS Remote Inspection Techniques
Cert No. 21-4996595-A
SKUP MIGAS NDT ★★

VISUAL INSPECTION REPORT

Photographic Support